#### 21 MARCH 2017

### **MEDIA RELEASE**

### FLIGHT ZL768 PROPELLER FOUND

Regional Express (Rex) has been advised today by the Australian Transport Safety Bureau (ATSB) that that the propeller assembly that separated from an aircraft operating Flight ZL768 on Friday 17 March 2017 has been found in the Georges River National Park about 18 km from Sydney Airport by the NSW Police Force Airwing (PolAir).

Rex's Chief Operating Officer Neville Howell said, "The propeller will be vital in assisting the ATSB with their investigations. Further technical updates will be provided as appropriate by the ATSB. On behalf of the Board, I wish to place on record our immense gratitude to PolAir for its utmost dedication, perseverance and professionalism in the search for the missing propeller without which the full ATSB investigations may be delayed by many days if not weeks."

Rex also takes this opportunity to correct certain gross inaccuracies in recent Seven News reports and other media:

## - that the aircraft should be diverted to Canberra in accordance with regulations.

As stated in our previous media release and as confirmed by the location of the propeller, the aircraft was some 20 km away from Sydney airport when the engine was shut down and the propeller separated from the aircraft. It would be ludicrous for the pilot to divert the aircraft 250 km to Canberra airport when Sydney airport was just 20 km away. The Company stands behind the decision made by the crew to continue to Sydney airport. This was the correct and safest decision and in full compliance with both regulatory and company requirements. Further, Sydney airport has a precision landing system, longer runway and more suitable runway orientation to cope with the prevailing strong winds.

# - that maintenance checks would have been able to detect the fault in the vulnerable propeller shaft.

It is premature to second guess the outcome of the ATSB investigations but on Rex's part, it has been fully compliant with the engineering inspections prescribed by General Electric (GE), the manufacturer of the engine assembly.

Finally, Rex wishes to clarify that it did not ground any of its aircraft. Rex has simply taken the precautionary measure to replace the gear boxes and shafts (of the same series as the separated propeller) of 5 aircraft, and this will be carried out over the next 2-3 days. Only minor disruptions are expected and affected passengers will be notified in advance.

Regional Express (Rex) is Australia's largest independent regional airline operating a fleet of more than 50 Saab 340 aircraft on some 1,500 weekly flights to 58 destinations throughout all states in Australia. In addition to the regional airline Regional Express, the Rex Group comprises wholly owned subsidiaries Pel-Air Aviation (air freight and charter operator), Air Link (Dubbo-based regional airline) and the Australian Airline Pilot Academy.

Rex Media Contact: Corporate Communications: +61 402 438 361 media@rex.com.au











